



Automotive, Industrial & Multimarket

Release Notes (V3.6 RTM)

Infineon TPM Professional Package

Version: 1.3

Date: 2009-08-06

<b>Dev. / Step Code:</b>	<b>Sales Code:</b>
<b>Status:</b>	<b>Date:</b> 2009-08-06
<b>Document:</b> IFX_ReleaseNotes_3.6.doc	<b>Created with:</b> Microsoft Office Word
<b>Author:</b> CCS PFS SW PC	<b>TEL.</b>
<b>Document path:</b>	

## REVISION HISTORY

<b>VERSION</b>	<b>DATE</b>	<b>CHANGE MADE BY</b>	<b>SECTION NUMBER</b>	<b>DESCRIPTION OF CHANGE</b>
1.0	2009-04-30	CCS PFS SW		V3.6 Beta IFX
1.1	2009-05-25	CCS PFS SW		V3.6 RC1 IFX
1.2	2009-07-21	CCS PFS SW		V3.6 RC2 IFX
1.3	2009-08-06	CCS PFS SW		V3.6 RTM IFX

## **Contents**

<b>1</b>	<b>Introduction .....</b>	<b>5</b>
<b>2</b>	<b>Release Notes .....</b>	<b>6</b>
2.1.1	Purpose of the build .....	6
2.1.2	Descriptive Name of Deliverable .....	6
2.1.3	Vendor Version Number .....	6
2.1.4	Short Description .....	6
2.1.5	Supported Languages .....	6
2.1.5.1	Supported Languages .....	6
2.1.6	Supported Platforms .....	6
2.1.6.1	Operating Systems .....	6
2.1.6.2	Compatibility requirements .....	7
2.1.6.3	Hardware Requirements .....	7
2.1.7	Known Observations from Test Report .....	8
2.1.7.1	Not supported functionality .....	8
2.1.7.2	Setup .....	8
2.1.7.3	Encrypting File System .....	8
2.1.7.4	PSD .....	9
2.1.7.5	Dictionary Attack .....	9
2.1.7.6	TNA .....	9
2.1.7.7	Settings Tool .....	10
2.1.7.8	TPM Interoperability .....	10
2.1.7.9	Miscellaneous .....	10
2.1.7.10	RSASecurID .....	11
2.1.7.11	Enhanced Authentication .....	11
2.1.8	Observations Fixed in this Release .....	12
2.1.8.1	RTM .....	12
2.1.8.2	RC2 .....	12
2.1.8.3	RC1 .....	12
2.1.9	Obsolete Observations .....	13



***Infineon TPM Professional Package***  
**Project Specific Documents**

---

2.1.10	Installation Instructions.....	13
2.1.11	WHQL Certification State .....	13
2.1.12	Co-requisite hardware or software .....	14
2.1.12.1	BIOS Requirements .....	14
2.1.12.2	Security Platform Chip .....	14
<b>3</b>	<b>Debug Versions.....</b>	<b>15</b>



## **1 Introduction**

This document provides information about the released version of the Infineon TPM Professional Package.

## **2 Release Notes**

### **2.1.1 Purpose of the build**

Version V3.6 RTM

### **2.1.2 Descriptive Name of Deliverable**

Infineon TPM Professional Package

### **2.1.3 Vendor Version Number**

Build: 03.60.2071.01

### **2.1.4 Short Description**

The Infineon TPM Professional Package Software is required to use your Security Platform Chip.

The Infineon TPM Professional Package Software is a TCG-compliant security solution for PCs.

### **2.1.5 Supported Languages**

#### ***2.1.5.1 Supported Languages***

BR	- Brazilian Portuguese
CH	- Chinese simplified
CHT	- Chinese Traditional
FR	- French
GR	- German
IT	- Italian
JP	- Japanese
KR	- Korean
RU	- Russian
SP	- Spanish

### **2.1.6 Supported Platforms**

#### ***2.1.6.1 Operating Systems***

Operating Systems (only for 32-bit product version with MS Internet Explorer):

- Microsoft Windows XP Professional Service Pack 3
- Microsoft Windows XP Home Edition Service Pack 3
- Microsoft Windows XP Media Center Edition 2005 Service Pack 3
- Microsoft Windows XP Tablet PC Edition 2005 Service Pack 3
- Microsoft Windows Server 2003 Service Pack 2

- Microsoft Windows Vista Service Pack 1
- Microsoft Windows Vista Service Pack 2
- Microsoft Windows Server 2008 Service Pack 2
- Microsoft Windows 7

Operating Systems (only for 64-bit product version with MS Internet Explorer):

- Microsoft Windows XP Professional x64 Edition Service Pack 3 (AMD64)
- Microsoft Windows Server 2003 x64 Edition Service Pack 2 (AMD64)
- Microsoft Windows Vista Service Pack 1
- Microsoft Windows Vista Service Pack 2
- Microsoft Windows 7

#### **2.1.6.2 Compatibility requirements**

- On a Windows 2000 based platform the Internet Explorer versions 5.0 and 6.0 (for SSL client side authentication via Infineon TPM User CSP) and the related versions of the Outlook Express (for S/MIME utilizing the Infineon TPM User CSP).
- Microsoft Office applications Microsoft Office 2000 SR-1, Microsoft Office XP, Microsoft Office 2003 (for S/MIME and SSL client side authentication via Infineon TPM User CSP).
- RSA SecurID  
RSA SecurID Software Token Software V3.0  
RSA SecurID ACE/Agent Software V5.0 for web access authentication  
RSA SecurID ACE/Agent Software V5.5 (plus patch: sdeap.dll V5.5.0.133) for remote access authentication
- Checkpoint  
Check Point VPN-1 SecuRemote/SecureClient NG with Application Intelligence (R55)  
Check Point VPN-1/FireWall-1 NG with Application Intelligence (R55)
- Adobe  
Acrobat 6.0 Professional for digitally signing of PDF documents as well as encryption.

#### **2.1.6.3 Hardware Requirements**

A PC capable to run one of the mentioned operating systems and equipped with an

- Infineon Security Platform Chip TPM SLD 9630TT1.1
- Infineon Security Platform Chip TPM SLB 9635TT1.2
- Broadcom TPM  
TPM FW-Version: 2.23  
Tested with HPQ Lakeport DC 7600

TPM FW-Version: 2.30  
Tested with HPQ Castles DC5750

- Winbond TPM  
TPM FW-Version: 2.16  
Tested with Desktop-System from Lenovo
- STMicro TPM  
TPM FW-Version: 4.30  
Tested with Dell-OptiPlex 755 System; BIOS-Version: A04 (11/05/07)

## **2.1.7 Known Observations from Test Report**

### **2.1.7.1 Not supported functionality**

- Archive with emergency recovery / password reset public key not selectable by Security Platform admin in platform init wizard

### **2.1.7.2 Setup**

- tpm00006568 Norton Antivirus 2005 complains about "malicious script" during installation. This is not seen with latest version of Norton Antivirus as with Norton Antivirus 2006
- tpm00006105 Warning message for unsupported operating systems  
Warning message for unsupported OS appears after the installation of prerequisites. According information is provided readme.txt as "Known Bugs and Limitation".
- tpm00006064 Fatal error during un-installation, If prerequisite package (e.g. VC++ Redistributable) is removed and then TPM software is un-installed. This is mentioned in readme.txt as "Known Bugs and Limitation".
- tpm00006051 InstallShield error 1152: Extracting prq file while passing incorrect parameter during setup.  
InstallShield error 1152 is displayed, if setup is launched with an invalid command line
- tpm00004826 If the software is installed on an operating system which does not support policies (e.g. XP Home), then the policies are missing after an upgrade to an operating system which supports this feature (e.g Vista Business Edition) and cannot be enabled by repair/modify of the installation. The software has to be uninstalled and reinstalled to enable the policies. This is mentioned in the Readme.txt
- tpm00000761 If the user changes the "Language for non-Unicode programs" in Control Panel, Regional settings, the Setup will run in that language and the shortcuts in the Start menu are created in the same language.

### **2.1.7.3 Encrypting File System**

- tpm00004960 UAC and BUP dialogs pop up when administrative user logs on if OS is upgraded from XP to Vista. Workaround mentioned in the Readme.txt file.

- tpm00004293 Reconfiguration of EFS on Windows 2003 Server  
Reconfiguration gets active after user has logged on again
- tpm00003414 1 minute delay during log off on W2K after using EFS.

#### **2.1.7.4 PSD**

- tpm00003566 PSD TNA Load  
If PSD is configured to "Load at logon" and user does not provide Basic User Password (BUP) during that process but chooses to load PSD additionally from TNA an error message "Personal Secure Drive is in use by another process" pops up. PSD can still be loaded by providing BUP in first BUP dialog.
- tpm00002404 Delete PSD with save of content  
More space than really required is requested since calculation of required space for copy contains also space used by file system and system volume information of PSD drive.

#### **2.1.7.5 Dictionary Attack**

- tpm00003550 Upgrade from Infineon TPM Professional Package 2.0 with IFX TPM1.2 to Infineon TPM Professional Package 3.0:  
TPM\_AT\_DELAY\_DOUBLE\_LOCK mode not set  
If a PC system with IFX 1.2 TPM is initially used with Infineon TPM Professional Package 2.0, the TPM chip is not initialized with TPM\_AT\_DELAY\_DOUBLE\_LOCK mode while upgrading to Infineon TPM Professional Package 3.0.  
If the user upgrades to Infineon TPM Professional Package 3.0, it does not behave the same as if he initialized with Infineon TPM Professional Package 3.0. TPM is still in TPM\_AT\_DELAY\_DOUBLE mode.  
This issue is mentioned in Readme file with according workaround.
- tpm00003623 No event log entry after entering DA defense mode
- tpm00003749 Reset of DA if Platform is in state "Initialized with Other OS" state  
Calling the Platform Initialization wizard with command line parameter /resetAttack to reset DA defense measures has no effect. TPM wizard ignores parameter and wants to initialize the platform.

#### **2.1.7.6 TNA**

- tpm00007901 Successive Log-on / user initialization / log-off of more than 150 different users sporadically reflects in an error: Cannot connect to TPM in TNA
- tpm00004357 Wrong tooltip in TNA if platform is temp disabled due to dictionary attack. TNA tooltip says "Ready to use" even when TPM 1.2 chip goes into defense state and DA mode of TPM 1.2 is configured to TPM\_AT\_DELAY\_DOUBLE\_LOCK.

### **2.1.7.7 Settings Tool**

- tpm00006609 The "X" on upper right corner of system message box is shown but does not work.  
If platform or user is not initialized, clicking on "User" page will display a dialog informing the user if he wants to initialize now. The "X" on upper right corner is shown but does not work on this dialog. This is only visible systems with Vista and AERO effects enabled and is an operating system issue. SW uses system message box which should handle this. The "x" button is not enabled if the message box has buttons other than "OK", "Cancel". It is by design from MS since Windows 2000.

### **2.1.7.8 TPM Interoperability**

- Potential interoperability issue between ST-Micro TPM v4.30 and other third party TPMs like Intel and Winbond in migration scenarios.  
Migration in "Migrate-Mode" (used in emergency recovery use case while restoring from system backup) and in "Re-Wrap-Mode" (used in migration use case) from STMicro TPM system to other third party TPM system fails, if STMicro TPM did not generated a "full qualified" basic user key (most significant bit is not set).
- tpm00006713 A TPM or TSS error occurs for STMicro TPM if TPM is disabled under Vista  
TPM SW is installed on a clean system and Chip is disabled in BIOS. If user starts the CPL as administrator and clicks any tab different to Info page a "TPM or TSS error occurred (0xe0283002)" message box pops up.
- tpm00006682 Interoperability between ST-Micro (TPM FW v3.11) and other none ST-Micro TPMs  
Migration from a ST-Micro TPM system to another TPM system is not possible. Migration wizard fails with authorization error for basic user password validation during import of migration archive on destination system. This error occurs even if user is migrating from user (a) to user (b) on the same ST-Micro system.  
Not an issue with STMicro TPM FW v4.30
- tpm00006671 Interoperability between ST-Micro and Winbond TPM system  
User initialized on a ST-Micro TPM system does not work in Winbond TPM system if roamed to Winbond system with Trusted Computing Management Server v1.0 in server mode or via emergency recovery restore in standalone mode.
- tpm00006510 Interoperability between ST-Micro and Broadcom TPM system  
User initialized on a ST-Micro TPM system does not work in Broadcom TPM system if roamed to Broadcom system with Trusted Computing Management Server v1.0 in server mode or via emergency recovery restore in standalone mode.

### **2.1.7.9 Miscellaneous**

- tpm00007911 "Restore All" fails if more than 150 different user are enrolled and backed up in system backup archive
- tpm00007764 Microsoft VPN connection when using EAP-TLS with certificates  
Issue is mentioned in readme.txt section 5.6.20

- tpm00007538 TPM small icon in control panel is shown without key image.
- tpm00007522 TPM icon 'expansion/compression' problem in Vista control panel  
No support for 'large' & 'Extra large' TPM icons in control panel.
- tpm00006486 F5 to refresh PSD configuration pages does not work  
F5 does not refresh list box on page "Configure your Personal Secure Drive"
- tpm00006093 Volume Shadow Copy Service (VSS) shows issue at Vista, Windows Server 2003 and XP when a PSD is loaded.  
With Vista System Restore is not using System Restore service, but is utilizing Volume Shadow Copy Service (VSS). As VSS is affected when a PSD is loaded, creation of restore points is also affected when PSD is loaded and selected for automatic restore points.
- tpm00005457 After installation of SW, the warning event, 3004 from Windows Defender, is found in the system event log. This is a behavior of Microsoft Windows Defender and a service request is pending at Microsoft regarding this issue.
- tpm00005451 Warning 1517 of application event log is recorded on every reboot.
- tpm00005450 Warning 1524 of application event log is recorded after EFS access.
- tpm00005420 Warning 541 of TBS is recorded when the system resume from S3 and / or S4
- tpm00004527 Status update in Security Platform Control panel is missing in case the BitLocker is managed from Vista BitLocker Control Panel.
- tpm00004526 Status update in TNA and the Security Platform Control panel is missing in case the TPM is managed from Vista TPM console/wizard. A possible workaround for Owner state : Restart system.
- tpm00004272 Basic User Password Dialog prevents Shutdown/Restart  
When the Basic User Key password is present, the user cannot perform Shutdown or Restart. However Standby and Hibernate can be performed.

#### **2.1.7.10 RSA SecurID**

- tpm00006110 RSA SecurID Software Token v3.07 does not load PKCS#11 crypto service provider.  
RSA provided a hot fix for Infineon (based on v3.07) that re-enables PKCS#11 support. But this hot fix does not work with Host Software versions 3.0 and higher. Presumably there will not be a version 3.08 of RSA SecurID.

#### **2.1.7.11 Enhanced Authentication**

- tpm00002809 Switch to "Enhanced Authentication" when BUK password has expired  
If BUK password has expired the BUK password has to be changed first before enhanced authentication can be enabled

## **2.1.8 Observations Fixed in this Release**

### **2.1.8.1 RTM**

- tpm00007975 Configuration of system back fails if system backup location is directly the root folder of a drive and not a sub-directory

### **2.1.8.2 RC2**

- tpm00007915 Cut text on Button Labels in Korean
- tpm00007912 Inconsistent notation of radio button in Help file
- tpm00007910 System backup created in wrong location if re-initialization is done by another administrative user after clearing TPM in BIOS
- tpm00007909 Too much text in bold in Brazilian help file section “Etapas Administrativas”
- tpm00007907 Inappropriate Japanese translations in Help file
- tpm00007900 Inappropriate Japanese translation in Summary page of Backup Wizard
- tpm00007899 Inconsistent Japanese translation of 'user' in InstallShield
- tpm00007894 Same Message display twice if re-initialization of user with advanced user wizard is done after TPM clear in BIOS
- tpm00007893 Localization of Japanese Readme
- tpm00007892 Irregular EFS behavior at a particular Power Transition Profile
- tpm00007891 Strange message when deleting PSD and giving a non-existent path for saving PSD content
- tpm00007889 System Backup Archive is not protected against encryption
- tpm00007887 Misspelling “Unhided” in Migration Wizard
- tpm00007869 User initialization fails for PSD if HD space is exactly on reserved limit for system drive

### **2.1.8.3 RC1**

- tpm00007848 Successive Log in / Log off for 150 different user and above results in Communication Problems with the TPM chip
- tpm00007829 CHT: Wrong text in Embedded Security restore wizard
- tpm00007789 Bitlocker link is available for Windows 7 Editions even if Bitlocker is not supported
- tpm00007788 Wrong Chinese simplified translation when ask to save Owner password during TPM initialization

- tpm00007720 Wrong contents in Japanese Help for User Policies from US

## **2.1.9 Obsolete Observations**

### **2.1.10 Installation Instructions**

The module <Setup.exe> installs the Infineon TPM Professional Package Software.

Installing Infineon TPM Professional Package Software requires administrative rights.

### **2.1.11 WHQL Certification State**

Guardionic Solutions has a signed contingency from Microsoft for its PSD.SYS driver that WHQL is not applicable to this driver. Contingency No: 622

## **2.1.12 Co-requisite hardware or software**

### ***2.1.12.1 BIOS Requirements***

BIOS ACPI plug and play support for the Security Platform Chip.

### ***2.1.12.2 Security Platform Chip***

- Security Platform Chip: TPM SLD 9630TT1.1  
Firmware: Version 1.05
- Security Platform Chip: SLB 9635TT1.2  
Firmware: Version 1.02

### 3 Debug Versions

PSD supports event logging also for debugging purposes.

The PSD event logging is controlled via registry entries at

HKEY\_LOCAL\_MACHINE\Software\Microsoft\Windows\CurrentVersion\App Paths\PSDapp

The event log level is set by the value 'EventLogging' as REG\_DWORD, this value is set at install time.

Following values are defined:

- No event log

0 No event log

1 Only error events

2 Error and warning events (**default** at installation)

3 Error, warning and information events

4 Error, warning, information and debug events ( EventDebugging value )

In case of debug events, an additional value 'EventDebugging' controls with module posts debug events as REG\_DWORD, one or more values can combined ( added ) together.

0x00000001 PSD.dll

0x00000002 PSDrt.exe

0x00000004 PSDsvc.exe

0x00000008 PSDCFGWZ.ocx

0x00000010 PSDShExt.dll

0x00000040 PSDrecovery.exe

0x00000100 unmount.exe ( only visible at uninstall time )

#### **Note:**

Enabling debug events for all modules will fill up the eventlog very fast.

Therefore the recommendation is to change the event log properties.

Increase the log size and enable the option "overwrite events as needed".