

**PBL00/01/20/21 W7 Drivers Status Ver.1.01**

Prepared by: Ellen Liang

Last update on 6/23/2011

Drivers	Provider	Operating System	MS-Logo Certified Ver. & Job ID	Current Testing. Ver.	Remark
Chipset (Intel Cougar Point HM65)	Intel	Windows 7 32	V9.2.0.1021		
		Windows 7 64	V9.2.0.1021		
Intel VGA (Intel UMA)	Intel	Windows 7 32	V8.15.10.2345 (15.22.0.2345) Intel HDMI Audio: V6.14.0.3074 (ID: 1447116)		
		Windows 7 64	V8.15.10.2345 (15.22.64.2345) Intel HDMI Audio: V6.14.0.3074 (ID: 1447116)		
NVIDIA VGA (NVIDIA N12P-GS / GV2 / GT)	NVIDIA	Windows 7 32	V8.17.12.6601 (266.01) Nvidia HDMI Audio: V1.1.12.0 (ID: 1435872)		
		Windows 7 64	V8.17.12.6601 (266.01) Nvidia HDMI Audio: V1.1.12.0 (ID: 1435872)		
Intel Rapid Storage Technology Driver	Intel	Windows 7 32	V10.1.2.1004 (Logo)		PV
		Windows 7 64	V10.1.2.1004 (Logo)		PV
Intel Management Engine Interface (1.5M)	Intel	Windows 7 32	V7.0.0.1144 (Logo)		PV Package: V7.0.4.1197
		Windows 7 64	V7.0.0.1144 (Logo)		PV Package: V7.0.4.1197
Audio (For PBL00/01) (Realtek ALC259-VB5-GR)	Realtek	Windows 7 32	V6.0.1.6225 (Logo) (ID: 1428756)	EQ -10dB & PC Beep disable	The driver package is only for this project. Please don't use this package to another
		Windows 7 64	V6.0.1.6225 (Logo) (ID: 1428756)	EQ -10dB & PC Beep disable	
Audio (For PBL20/21) (Realtek ALC259-VB5-GR)	Realtek	Windows 7 32	V6.0.1.6225 (Logo) (ID: 1428756)	PC Beep disable	The driver package is only for this project. Please don't use this package to another
		Windows 7 64	V6.0.1.6225 (Logo) (ID: 1428756)	PC Beep disable	
LAN (Realtek Gigabit RTL8111E Realtek 10/100 RTL8105E)	Realtek	Windows 7 32	V7.034.1130.2010 (Logo) (ID: 1434356)		
		Windows 7 64	V7.034.1130.2010 (Logo) (ID: 1434356)		
WLAN (Atheros HB95)	Atheros	Windows 7 32	V8.0.0.335 (Logo) (ID: 1403639)		
		Windows 7 64	V8.0.0.335 (Logo) (ID: 1403639)		
WLAN (Realtek RTL8188CE)	Realtek	Windows 7 32	V1005.8.1101.2010 (Logo) (ID: 1431199)		
		Windows 7 64	V1005.8.1101.2010 (Logo) (ID: 1431199)		
WLAN (Realtek RTL8191SE)	Realtek	Windows 7 32	V2017.0.0611.2010 (Logo) (ID: 1410775)		
		Windows 7 64	V2017.0.0611.2010 (Logo) (ID: 1410775)		
WLAN+BT Combo (Broadcom WN7811BTA-LF-CP)	Broadcom	Windows 7 32	WLAN: V5.60.350.21 (Logo) (ID: 1417488)		
			BT: V6.3.0.7000 (Logo) (ID: 1427796)		
		Windows 7 64	WLAN: V5.60.350.21 (Logo) (ID: 1417488)		

		Windows 7 32	BT: V6.3.0.7000 (Logo) (ID: 1427796)		
WLAN+BT Combo (Realtek+CSR)	Realtek	Windows 7 32	WLAN: V1005.8.1101.2010 (Logo) (ID: 1431199)		
			BT: V3.0.12.285 (Logo)		
		Windows 7 64	WLAN: V1005.8.1101.2010 (Logo) (ID: 1431199)		
			BT: V3.0.12.285 (Logo)		
WLAN+BT Combo (Intel Centrino Wireless-N 1030 w/ WiDi) For PBL00 only	Intel	Windows 7 32	Proset: V14.0.3 (Logo)		
			BT driver: V1.0.2.0158 (Logo)		
		Windows 7 64	BT 3.0: V1.0.0.0135 (Logo)		
			WiDi: V2.0.30.0		Package: V2.0
		Windows 7 32	Proset: V14.0.3 (Logo)		
			BT driver: V1.0.2.0158 (Logo)		
		Windows 7 64	BT 3.0: V1.0.0.0135 (Logo)		
			WiDi: V2.0.30.0		Package: V2.0
USB 3.0 (Renesas uPD720200A)	Renesas	Windows 7 32	V2.0.34.0 (Logo) (ID: 1442151)		
		Windows 7 64	V2.0.34.0 (Logo) (ID: 1442151)		
Smart Card Reader (For PBL20/21) (Alcor AU9540)	Alcor	Windows 7 32	V1.7.10.0 (Logo) (ID: 1432906)		
		Windows 7 64	V1.7.10.0 (Logo) (ID: 1432906)		
TPM (For PBL20/21) (Infineon SLB 9635)	Infineon	Windows 7 32	V3.6 (ID: 1274819)		
		Windows 7 64	V3.6 (ID: 1274819)		
3 IN 1 Card Reader (Realtek RTS5138-GR)	Realtek	Windows 7 32	V6.1.7600.30124_noD3 (Logo) (ID: 1425960)		
		Windows 7 64	V6.1.7600.30124_noD3 (Logo) (ID: 1425960)		
Touch Pad (Synaptics TM-01146-005 / TM-01103-002)	Synaptics	Windows 7 32	V15.1.2.0 (Logo) (ID: 1426810)		
		Windows 7 64	V15.1.2.0 (Logo) (ID: 1426810)		
WebCam (13.3" Liteon 10P2SF018 0.3M)	Liteon	Windows 7 32	Native		
		Windows 7 64	Native		
WebCam (13.3" Liteon 10P2TF105 1.3M)	Liteon	Windows 7 32	Native		
		Windows 7 64	Native		
WebCam (13.3" D-Max GAA-061002-C1A 0.3M)	D-Max	Windows 7 32	Native		
		Windows 7 64	Native		
WebCam	D-Max	Windows 7 32	Native		

(13.3" D-Max GAA-866402-C1A 1.3M)	D-Max	Windows 7 64	Native		
WebCam (13.3" Suyin CN031A-J13C-HN01 0.3M 13.3" Suyin CN1316-J13C-HN01 1.3M 15.6" Suyin CN2015-J13C-OV01 2.0M)	Suyin	Windows 7 32	Native		
		Windows 7 64	Native		
WebCam (15.6" Liteon 09P2BF122A 1.3M)	Liteon	Windows 7 32	Native		
		Windows 7 64	Native		
WebCam (15.6" Liteon 10P2SF215 2.0M)	Liteon	Windows 7 32	Native		
		Windows 7 64	Native		
WebCam (15.6" D-Max GAA-063108-C1A 1.3M)	D-Max	Windows 7 32	Native		
		Windows 7 64	Native		
WebCam (15.6" Primax 50-70490CPC8 1.3M)	Primax	Windows 7 32	Native		
		Windows 7 64	Native		
Wireless Select Enable/Disable (WSED)	Compal	Windows 7 32	V0.0.0.13C		
		Windows 7 64	V0.0.0.13C		
Instant Message (For PBL00/01)	Compal	Windows 7 32	V0.0.0.9		
		Windows 7 64	V0.0.0.9		
Num Lock (For PBL00/01)	Compal	Windows 7 32	V0.0.0.3C		
		Windows 7 64	V0.0.0.3C		
Microsoft Hotfix	Microsoft	Windows 7 32	KB974476-v2-x86		
		Windows 7 64	KB974476-v2-x64		
Microsoft Hotfix	Microsoft	Windows 7 32	KB975538-x86		
		Windows 7 64	KB975538-x64		
Microsoft Hotfix	Microsoft	Windows 7 32	KB978258-x86		
		Windows 7 64	KB978258-x64		
Microsoft Hotfix	Microsoft	Windows 7 32	KB2482122-x86		
		Windows 7 64	KB2482122-x64		