

QAL30/31/50/51 W7 Drivers Status Ver.1.00

Prepared by: Ellen Liang

Last update on 03/14/2012

Drivers	Provider	Operating System	Driver version	Driver Package Ver.	Remark
Chipset (Intel Panther Point HM76/HM75/HM70)	Intel	Windows 7 32	V9.3.0.1020 (PV)	Kit 41685	
		Windows 7 64	V9.3.0.1020 (PV)	Kit 41685	
Intel VGA (Intel UMA)	Intel	Windows 7 32	V8.15.10.2669 (15.26.6.2669) Intel HDMI Audio: V6.14.0.3090	Kit 43203	PV customized inf
		Windows 7 64	V8.15.10.2669 (15.26.6.64.2669) Intel HDMI Audio: V6.14.0.3090	Kit 43204	PV customized inf
NVIDIA VGA (NVIDIA N13P-LP / GS / GT)	NVIDIA	Windows 7 32	V8.17.12.9601 (Logo) Nvidia HDMI Audio: V1.3.11.1		
		Windows 7 64	V8.17.12.9601 (Logo) Nvidia HDMI Audio: V1.3.11.1		
Intel Rapid Storage Technology Driver	Intel	Windows 7 32	V11.1.0.1006 (PV)	Kit 43186	
		Windows 7 64	V11.1.0.1006 (PV)	Kit 43186	
Intel Management Engine Interface (1.5M)	Intel	Windows 7 32	V8.0.0.1262 (PV)	Kit 43289	Package: 8.0.3.1427
		Windows 7 64	V8.0.0.1262 (PV)	Kit 43289	Package: 8.0.3.1427
Audio (Realtek ALC259Q)	Realtek	Windows 7 32	Driver: V6.0.1.6505 (Logo)		The driver package is only for this project.
			SRS: V1.12.12.0		
		Windows 7 64	Driver: V6.0.1.6505 (Logo)		The driver package is only for this project.
			SRS: V1.12.12.0		
LAN (Realtek Giga RTL8111E-VL-CGT)	Realtek	Windows 7 32	V7.48.823.2011 (Logo)		
		Windows 7 64	V7.48.823.2011 (Logo)		
3 IN 1 Card Reader (Realtek RTS5129)	Realtek	Windows 7 32	V6.1.7601.39022 (Logo)		
		Windows 7 64	V6.1.7601.39022 (Logo)		
Touch Pad (Synaptics TM-01694-001)	Synaptics	Windows 7 32	V15.3.21.0 (Logo)		
		Windows 7 64	V15.3.21.0 (Logo)		
Touch Pad (ElanTech S8742D-5300)	ElanTech	Windows 7 32	V10.10.2.5 (Logo)		
		Windows 7 64	V10.10.2.5 (Logo)		
WLAN (Atheros HB95) PK29200GJ00	Arcadyan	Windows 7 32	V8.0.0.379 (Logo)		
		Windows 7 64	V8.0.0.379 (Logo)		

WLAN (Atheros AR9280) PK29200MG00	Azureware	Windows 7 32	V8.0.0.379 (Logo)		
		Windows 7 64	V8.0.0.379 (Logo)		
WLAN (Realtek RTL8191SE) PK29200JK00	Realtek	Windows 7 32	V2017.0.0611.2010 (Logo)		
		Windows 7 64	V2017.0.0611.2010 (Logo)		
WLAN (Realtek RTL8188CE) PK29200JY00	Realtek	Windows 7 32	V1005.28.1006.2011 (Logo)		
		Windows 7 64	V1005.28.1006.2011 (Logo)		
WLAN+BT Combo (Broadcom F16CP7811009J) PK320003M00	Arcadyan	Windows 7 32	WLAN: V5.100.82.112 (Logo)		
			BT: V6.5.1.2321 (Logo)	V6.5.1.2410 (Logo)	
		Windows 7 64	WLAN: V5.100.82.112 (Logo)		
			BT: V6.5.1.2321 (Logo)	V6.5.1.2410 (Logo)	
WLAN+BT Combo (Atheros F16CP7811013J) PK320005I00	Arcadyan	Windows 7 32	WLAN: V9.2.0.470 (Logo)		
			BT: V7.4.0.115 (Logo)		
		Windows 7 64	WLAN: V9.2.0.470 (Logo)		
			BT: V7.4.0.115 (Logo)		
WLAN+BT Combo (Realtek+CSR)	Realtek	Windows 7 32	WLAN: V1005.28.1006.2011 (Logo)		
			BT: V3.0.3.303 (Logo)	V3.0.13.307	
		Windows 7 64	WLAN: V1005.28.1006.2011 (Logo)		
			BT: V3.0.3.303 (Logo)	V3.0.13.307	
Intel WiDi (Intel Centrino Centrino 2200 / 2230 / Advanced-N 6235) Centrino 2200: WLAN only	Intel	Windows 7 32	WiFi: V15.0.1.1 (PV)	Kit 41254	
			BT: V1.0.13.30079 (PV)	Kit 41033	
			WiDi: V3.0.12.0 (PV)	Kit 40934	
		Windows 7 64	WiFi: V15.0.1.1 (PV)	Kit 41254	
			BT: V1.0.13.30079 (PV)	Kit 41033	
			WiDi: V3.0.12.0 (PV)	Kit 40934	
USB 3.0 (Intel intergrated)	Intel	Windows 7 32	V1.0.3.214 (PV)	Kit 41901	
		Windows 7 64	V1.0.3.214 (PV)	Kit 41901	
Smart Card Reader (Alcor AU9540A51)	Alcor	Windows 7 32	V1.7.21.0 (Logo)		
		Windows 7 64	V1.7.21.0 (Logo)		
TPM (Infineon SLB-9635)	Infineon	Windows 7 32	V3.6		
		Windows 7 64	V3.6		
Finger Print	AuthenTec	Windows 7 32	Driver: V3.2.2.1072		
			AP: V7.1.5.13		

(AuthenTec AES1660)	AuthenTec	Windows 7 64	Driver: V3.2.2.1072 AP: V7.1.5.13		
WebCam (14" D-Max GAA-586604-C1A 0.3M)	Compal	Windows 7 32	Native		
		Windows 7 64	Native		
WebCam (14" Lite-on 11P2SF013 0.3M)	Compal	Windows 7 32	Native		
		Windows 7 64	Native		
WebCam (14" Fitolink CAM5068 0.3M)	Compal	Windows 7 32	Native		
		Windows 7 64	Native		
WebCam (14/15.6" D-Max GAA-588707-C1A 1.3M)	Compal	Windows 7 32	Native		
		Windows 7 64	Native		
WebCam (14/15.6" Suyin HF1316-T803-HM08 1.3M)	Compal	Windows 7 32	Native		
		Windows 7 64	Native		
WebCam (15.6" Suyin HF2015-J13C-HN03 2.0M)	Compal	Windows 7 32	Native		
		Windows 7 64	Native		
WebCam (15.6" D-Max GAA-588801-C1A 2.0M)	Compal	Windows 7 32	Native		
		Windows 7 64	Native		
Wireless Select Enable/Disable (WSED)	Compal	Windows 7 32	V0.0.0.13C		
		Windows 7 64	V0.0.0.13C		
Power USB	Compal	Windows 7 32	V0.0.0.1		
		Windows 7 64	V0.0.0.1		
Battery Optimization	Compal	Windows 7 32	V0.0.0.4		
		Windows 7 64	V0.0.0.4		
Microsoft Hotfix	Compal	Windows 7 32	KB2482122-x86		For Broadcom FI6CP7811009J Combo
		Windows 7 64	KB2482122-x64		For Broadcom FI6CP7811009J Combo
Microsoft Hotfix	Compal	Windows 7 32	KB2519736-x86		For 0x7F
		Windows 7 64	KB2519736-x64		For 0x7F